United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SASBINE

This certificate, issued to

Canadair Challenger Service Center Bradley International Airport Windsor Locks, Connecticut 06096

cortifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part

25 of the Federal Aviation

Regulations.

Original Product - Type Certificate Number:

A21EA

Make:

Canadair Challenger

Modeli

CL-600-1A11, -2A12, -2B16

Description of Trype Design Change:

Replacement of total temperature sensor Rosemount P/N 102CP2AF with Rosemount P/N 102AH2AF or replacement of Rosemount P/N 102CP2AG with Rosemount P/N 102AH2AG.

Limitations and Conditions:

This modification should not be incorporated in any aircraft of this specific model on which other approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of those previously incorporated approved modifications will not introduce any adverse effect upon the airworthiness of the aircraft.

This certificate and the supporting data which is the bosis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

June 24, 1987

Date reissued:

Date of issuance:

June 17, 1988

Date amended:

By direction of the Administrator

Ronald L. Vavruska gnowadager.

Boston Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.